

Download Saturn Repair Manual 2000 SL2 Water Pump

I also have a 2000 Saturn SL2 with the Twin Cam 16 valve engine. It's had a problem with overheating. The cooling fan doesn't come unless the air condition is on. A "tune up" is a misnomer these days on 21st century cars- they are engineered to go tens of thousands of miles without any attention other than oil changes- regular servicing happens at 30, 60, 90,000 miles and involves many things by a competent mechanic- what is a "tune up"? 2001 Saturn SL2 transmission will slam when placed in reverse replaced fluids and let run in reverse position with emergency brake set and backed up against a tree to try and clean valve body - no success. 1999 SL2 High Engine Coolant Temperature/ Automatic Transaxle Fluid Temperature and Low Coolant Level Light come on - Answered by a verified Saturn Mechanic